



The Brumbaugh House Streetview - exterior last painted in 2012



The Brumbaugh House - Elkridge Heights side



The Back of the Brumbaugh House



Plaque Outside the Office Door



Porch was renovated in 2019, except roof



Paint in bad shape




Dr Brumbaugh's waiting room



Dr. Brumbaugh's Office - notice crumbling plaster



The Kitchen, view 1



The Parlor



The Kitchen, View 2



The Hallway



The Dining Room (Now the Main Display Room)




Records Room - EHS Records



Downstairs Bathroom




Example of an Old Display - we want better!




Another angle of the Records Room




It is just a 2-piece (powder room)



Another Angle of the Main Display Room




Records Room - Dr. B's medical books and records



The Stairway - Watch Your Head!



Upstairs Room - could be a display room



Maps and stuff temporarily moved



Little Room of Sellables and Such-not



Some stuff in the room above



The curator's office



Archives



Upstairs bathroom and Peek into the upstairs kitchen



The Carriage House



Looking back at the Brumbaugh House



It needs a new roof



Accessible backdoor - if cleaned up



Clawfoot tub upstairs



Other angle of the carriage house



Office Door - goodbye until next time!